



Worldwide Spares Supplier
TPE331 | APU | Airframe
Over 25 Years of Support

For additional information please contact us toll free at 800-949-7458 or 417-781-TECI (8324).

Model: TPE331-10-511M

S/N: P-38082C

P/N: 3102180-2

Maintenance Prgm: 7000 TBO w/o gbi

Reason for Removal

TSN: 10813.3

CSN: 11525

TSO: 4376.6

CSO: 5256

TSCAM:

CSCAM:

TSHSI: 782.2

CSHSI: 735

TSGBI:

CSGBI:

Life Limited Items

Part Number	Description	CSN	TSN	CR	TR	Limit
3107079-1	1st T-Wheel	13206		6794		20000
3108125-1	Blades		4373.6			
3102106-10	2nd T-Wheel	5382		6618		12000
3102655-2	3rd T-Wheel	177		5823		6000
	3rd Stator					
3101519-4	Seal Plate	11525		8475		20000
3108182-2	1st Impeller	5256		24744		30000
893482-5	2nd Impeller	25		11475		11500
897801-12	Fuel Control		627.1			
897400-5	Fuel Pump		2038.9			
895481-17	Prop Pitch		4373.6			
897410-16	Prop Governor		822.3			
	Flow Divider					
394230-9-1	Fuel Shutoff		746.1			
3101726-3	Torque Sensor		4373.6			
3101405-1	Compressor Brg		1854.5			
missing	Torque Limiter					

Notes

27 Oct 2017 Long term by CDAS

19 May 2010 Low Power repair by SAI at TSN 10545.5 and CSN 11373

17 Aug 2006 Hot Section at TSN 10031.1 and CSN 10790

04 Nov 1998 OH by Allied Signal PHX at TSN 6439.7 and CSN 6269

Turbine Engine Consultants, Inc
2707 E 32nd St.
Joplin, MO 64804
800-949-7458 / 417-781-TECI (8324)
<http://www.teci.com>