



Worldwide Spares Supplier  
TPE331 | APU | Airframe  
Over 25 Years of Support

For additional information please contact us toll free at 800-949-7458 or 417-781-TECI (8324).

**Model:** TPE331-10R-511C  
**S/N:** P-37456C  
**P/N:** 3102170-6

**Maintenance Prgm:** 7000 tbo

**Reason for Removal:** Return off lease, 14 FEB 17

**TSN:** 5880.6  
**CSN:** 6770  
**TSO:** 613.9  
**CSO:** 626

#### Life Limited Items

Part Number	Description	CSN	TSN	CR	TR	Limit
3107079-1	1st T-Wheel	6770		13230		20000
3108125-1	Blades		613.9			
3102106-7	2nd T-Wheel	2515		7085		9600
3102655-2	3rd T-Wheel	2465		3535		6000
3102483-1	Seal Plate	2453		17547		20000
3108182-2	1st Impeller	626		29374		30000
893482-3	2nd Impeller	42		11458		11500
897801-17	Fuel Control		4715.7	TSO	2284.3	7000
897390-8	Fuel Pump		1386.4	TSO	5613.6	7000
895481-22	Prop Pitch		298.8	TSO	6701.2	7000
897751-1	Prop Governor		613.9	TSO	6386.1	7000
394230-9-1	Fuel Shutoff		628.8	TSO	6371.2	7000
3101726-3	Torque Sensor		613.9	TSO		
3103708-1	Compressor Brg		613.9	TSO	6386.1	7000
895380-4	Torque Limiter		2092.3	TSO	4907.7	7000

#### Notes:

2 Sep 2105 test and repair by CD Aviation Services  
25 Nov 08 Overhaul by Standard Aero LAX TSN 5266.7 & CSN 6144

Turbine Engine Consultants, Inc  
2707 E 32<sup>nd</sup> St.  
Joplin, MO 64804  
800-949-7458 / 417-781-TECI (8324)  
<http://www.teci.com>