



Worldwide Spares Supplier
TPE331 | APU | Airframe
Over 25 Years of Support

For additional information please contact us toll free at 800-949-7458 or 417-781-TECI (8324).

Model: TPE331-10-511M

S/N: P-38080C

P/N: 3102180-2

Maintenance Prgm:

Reason for Removal

TSN: 3995.4

CSN: 4282

TSO: 1845.1

CSO: 1603

TSCAM:

CSCAM:

TSHSI:

CSHSI:

TSGBI:

CSGBI:

Life Limited Items

Part Number	Description	CSN	TSN	CR	TR	Limit
3101603-1	1st T-Wheel	5853		14147		20000
3101512-1	Blades					
3102106-7	2nd T-Wheel	2194		7406		9600
3102655-2	3rd T-Wheel	1548		4452		6000
	3rd Stator					
3102483-1	Seal Plate	1603		18397		20000
896223-3	1st Impeller	669		4731		5400
893482-3	2nd Impeller	49		11451		11500
897801-12	Fuel Control		178.3			
897400-5	Fuel Pump					
895481-17	Prop Pitch		1509.7			
897410-16	Prop Governor		1113.6			
	Flow Divider					
394230-9-1	Fuel Shutoff		389			
3101726-3	Torque Sensor		1113.6			
	Compressor Brg					
	Torque Limiter					

Notes

23 Feb 2017 Removed from Thrush

23 Feb 1999 Gearbox repair by Garrett Houston at TSN 2881.8 and CSN 3508

8 Aug 1989 OH by Allied Signal at TSN 2150.3 and CSN 2679

Turbine Engine Consultants, Inc
2707 E 32nd St.
Joplin, MO 64804
800-949-7458 / 417-781-TECI (8324)
<http://www.teci.com>